

EPA Lead and Copper Rule Revision Required Service Line Inventory Statement:

HC MUD 383 has completed the Lead & Copper Inventory as required by the EPA. Through records research and field investigation of the distribution system, it has been determined that the system has no lead service lines or galvanized requiring replacement service lines. The system has been determined as a non-lead community. If you would like a copy of the Lead & Copper Inventory, please submit your request to HAR383@txdistricts.info.